Spectralink 75-76-77x2-Series

Release Notes Q1, 2016

Firmware Version PCS 16B

Table of Contents

Introduction

Terms and Definitions

HMP   Handset Management Program for Spectralink 75-, 76-Series and 77-Series

KWS   KIRK Wireless Server

MSF   Message Service Format. Contact compliance@spectralink.com for detailed information

PBX   Private Branch Exchange (IP/Lync/CUCM/Analog)

PCS   Product Change Status

P-ID   Production Identification

Release

These combined release notes apply to the released versions of firmware for the Spectralink 75-76-77x2-Series. This version specifically applies to version PCS 16B of the firmware. The release is a main release that replaces the PCS 15Q release as the latest generally available (GA) release.

The current handset firmware PCS information can be found in Menu/Status/General information under Firmware. The version consists of two digits and two letters. The digits and first letter forms the major version. The last letter, which can be either small or capital, is the minor version.

Minor versions are irrelevant for these release notes and are therefore left out.

Driver for the Handset Management Cradle.

Ensure that the latest driver is installed. You can download it here>>

Upgrading the Handset

Download the latest software for (product name) from the Spectralink Support Portal). Sign up for Spectralink's technical newsletter Tech Point to get updated on new software releases and technical information.

Also, you can quickly and easily update your handset(s) with the Spectralink Handset Software Updater.

Changes

Version PCS 16B – Q1, 2016

Added or Changed Features

- Updated battery parameters for optimal utilization of the battery capacity.
- Added CUCM conference join.
- Added service menu *99947* to set absent mode.
- Added idle screen battery indicator.
- Improved Bluetooth audio quality.
- Improved backwards compatibility for Handset Management Tool, and support for adjusting ear gain, microphone attenuation, and reading custom logo.
- Speed dial entry is now deleted if corresponding phone book contact is deleted.
- Fixed setting the time and date manually.
- Fixed LEDs blinking on MenuSelectSetupReq and AsciiStrReq.

Version PCS 15Q – Q4, 2015

Added or Changed Features

- Added Presence menu for supported servers.
- Adding ringtone 11 and 12 for noisy environments.
- Improvements to handover in multicell environments.
- Improved battery time.
- Fixed writing shortcuts to EEPROM.
- In-band tone could hang and start on new call. (DECTESC-624)
- Changed "battery low" and "out-of-range" tones to in-band busy tone if in call.
- Alerting will now stop when text calls are accepted.
- Fixed internal and external alert pattern for messages.
- When phonebook search buffer is full do not continue accepting input.
- Call Control: Fixed idle display. External, Internal, Knock-knock and silent alerting will play correctly.
- Don't turn on backlight when trickle charging on/off.